

...the heart of your aircraft®



Concorde Battery Corporation
 2009 San Bernardino Road
 West Covina, CA 91790
 Phone (800) 757-0303 or (626) 813-1234
 Fax (800) 237-4209 or (626) 813-1235
 Email: customer-service@concordebattery.com
 http://www.concordebattery.com

An ISO 9001:2008 + AS9100 Certified Company

Eligibility List

Revision: EL-77 (Revised: 9-24-2014)

(Contact Concorde factory or consult website for latest revision number)

The item or technical data contained herein has been reviewed and approved for general release on the basis that it contains no export controlled information.

FAA Approval Information

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Aerofab Inc.	(See Revo Inc.)				
Agusta	A109C, A109E, A119, AW119 MKII (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR09360RC	RG-407	FAA-PMA Supplement No. 57, dd 06/16/03 and FAA TSO-C173 (Amendment to STC to add AW119 MK II on 01/15/10)
Agusta	A119, AW119 MKII (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR04007AT	RG-427 6228 (placard)	FAA-PMA Supplement No. 104, dd 09/16/13 & P/N RG-427 is FAA TSO-C173 authorized
Agusta	A109A, A109C, A109E (To replace nickel-cadmium battery – Contact Rotorcraft for details prior to battery purchase)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03 and FAA TSO-C173
Agusta	AB139, AW139 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303 (DECA Aviation Eng. Ltd.)	STC# SR03072NY	RG-380E/44L or RG-380E/60L	FAA TSO-C173
Airbus Group Supply	TBM 700 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA00775LA	RG-380E/44	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Airbus Helicopters	AS350 B, BA, B1, B2, B3, D (To replace p/n 151CH-1 nickel-cadmium battery as a substitute for p/n 1606-1 per Airbus STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-350	FAA-PMA Supplement No. 52, dd 02/18/03 and FAA TSO-C173
Airbus Helicopters	AS350 B, B1, B2, BA, C, D, D1 (To replace p/n 1606-1 nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09185RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98 and FAA TSO-C173
Airbus Helicopters	AS355 E, F, F1, F2, N (To replace p/n 1606-1 nickel-cadmium battery)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09186RC	RG-355	FAA-PMA Supplement No. 35, dd 03/06/98 and FAA TSO-C173
Airbus Helicopters	BK-117-A-1, -A-3, -A-4, -B-1, -B-2, -C-1 (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest (800) 833-5422 (713) 644-2290	STC & STA# SR09034RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95 and FAA TSO-C173
Airbus Helicopters	BO-105C & BO-105S (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest (800) 833-5422 (713) 644-2290	STC# SR09016RC	RG-390E	FAA-PMA Supplement No. 21, dd 11/15/95 and FAA TSO-C173
Airbus Helicopters	EC130B4 (To replace p/n 151CH-1 nickel-cadmium battery – Contact Rotorcraft for details)	Rotorcraft Support (818) 997-7667	STC# SR02073LA	RG-350	FAA-PMA Supplement No. 88, dd 07/15/09 and FAA TSO-C173
Alon	(See Univair)				
American Champion	7ECA, 7GCAA, 7KCAB	American Champion (800) 223-9381 (262) 534-6315	TC# A-759	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
American Champion	8GCBC, 8KCAB	American Champion (800) 223-9381 (262) 534-6315	TC# A-21CE	RG-25	FAA-PMA Supplement No. 31, dd 06/03/97
Aviat Inc. / Sky Int'l	Aviat Model A-1A, A-1B Aviat Pitts Model S-2C	Aviat Inc. / Sky International (307) 885-3151	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 42, dd 08/06/01
Aviat Inc. / Sky Int'l	Aviat Model A-1; Aviat Pitts Models S-1S, S-1T, S-2, S-2A, S-2S, S-2B	Aviat Inc. / Sky International (307) 885-3151	TC# A22NM & A8SO	RG-25	FAA-PMA Supplement No. 18, dd 08/02/95
Avions de Transport Regional (ATR)	ATR42 Series; ATR72 Series (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST03930AT (Kit)	RG-380E/44 (Main) RG-42 (Emergency) 7945 (Dummy temp. sensor); 6716 (Placard)	FAA-PMA Supplement No. 97, dd 09/28/11 & P/N RG-380E/44 and RG-42 are FAA TSO-C173 authorized
Beechcraft Corp.	MU-300-10, 400, 400A (To replace nickel-cadmium battery – Contact Beechcraft for details prior to battery purchase)	Beechcraft (800) 256-6012 (404) 699-9228	STC# SA2494SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Beechcraft Corp.	A200CT (Military), RC-12K	Wilco (800) 767-7593 (316) 943-9379	FAA Design Approval	TS-C6 (Sold as 5-0154, Kit, Temp. Sensor, TS-C6)	FAA-PMA Supplement No. 70, dd 05/28/04

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Beechcraft Corp.	Kingair 65-90, 65-A90, B90, C90, E90, F90, 99, A100, B100, 200, 300, MU-300-10, 400, 400A, 400T, (T-1A) Concorde (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Beechcraft Corp.	Kingair 65-90, 65-A90, 65-A90-1 (JU-21A, U-21A, RU-21A, RG-21D, U-21G, RU-21H), 65-A90-4 (RU-21E, RU-21H), B90, C90, 65-A90-2 (RU-21B), 65-A90-3 (RU-21C), E90, H90 (T-44A), C90A, F90, 99, 99A, 99A (FACH), 100, A99, A99A, A100 (U-21F), B99, A100A, B100, C99, 200 (A100-1(U-21J)), A200C (UC-12B), 200C, B200, B200C (C-12F, UC-12F, UC-12M, C-12R), A200 (C-12A, C-12C), 200T, 200CT, A200CT (C-12D, C-12F, FWC-12D, RC-12D, RC-12F, RC-12G, RC-12H, RC-12K, RC-12P, RC-12Q), B200CT, B200T, 300, 300LW, B300, B300C, 1900, 1900C, 1900C (C-12J), 1900D (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA01260WI	RG-380E/40L RG-380E/40K RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 73, dd 08/11/04 and FAA TSO-C173
Beechcraft Corp.	Kingair 65-90, 65-A90, 65-A90-1 (Military U-21A, RU21A, RU21D, JU21A, U-21G, RU21H/GRV), 65-A90-4 (Military RU21E, RU21H/GRV & IV), B90, C90, 65-A90-2 (Military RU-21B), 65-A90-3 (Military RU-21C), E90, H90, (Military T-44A), C90A, F90, 99 & 99A, (Military 99A), 100, A99, A99A, A100 (Military U-21F), B99, A100A, B100, C99, 200, A200C, (Military UC-12), 200C, B200, B200C, (Military C12F, UC-12F & UC-12M), A200 (Military C-12A, C-12C), 200T, 200CT, A200CT (Military C-12D, FWC-12D, RC-12D, C-12F, RC-12G, RC-12H), B200CT, B200T, 200T, A100-1 (Military U-21J), A200CT (Military RC-12K), 1900, 1900C (Bladder Fuel), 1900C (Wet Wing), 1900C (Military C-12J), 1900D, 300, 300LW, B300, B300C, (S/N: FM-1 & subsequent, FN-1 & subsequent) (To replace nickel-cadmium battery – Contact Wilco for details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00741WI	RG-380E/40K RG-380E/44K RG-380E/60K	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02 and FAA TSO-C173
Beechcraft Corp.	200, 300, & B300 Series (To replace nickel-cadmium battery – Contact Beechcraft for details prior to battery purchase)	Beechcraft (800) 256-6012 (404) 699-9228	STC# SA2699SO	RG-380E/40B	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Beechcraft Corp.	400A (S/N RK-98 and after) (To replace Hawker Beechcraft part no. – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/40L	FAA-PMA Supplement No. 49, dd 1/23/03 and FAA TSO-C173
Beechcraft Corp.	Hawker 1000 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00640LA (Kit)	RG-380E/60K	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Beechcraft Corp.	BH.125 Series 1A, 1A/522, 1A/R-522, 1A/S-522; Series 3A, 3A/R, 3A/RA, BH.125 400A, 600A, HS.125 600A, 700A, BAe 125-800A; Hawker 800, 800XP (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00415LA	RG-390E	FAA-PMA Supplement No. 39, dd 04/23/99 and FAA TSO-C173
Beechcraft Corp.	DH.125 Series, HS.125 Series, BH.125 Series (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase) (STC to replace emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01223WI	RG-125	FAA-PMA Supplement No. 65, dd 01/30/04 and FAA TSO-C173
Beechcraft Corp.	400A Series (S/N's RK-98 and after) (To replace 38Ah lead-acid battery – Contact Beechcraft for details prior to battery purchase)	Beechcraft (800) 256-6012 (404) 699-9228	STC# ST02506AT	RG-380E/44 RG-380E/44L RG-380E/60L	FAA-PMA Supplement No. 44, dd 06/13/02 and FAA TSO-C173
Beechcraft Corp.	35, A35, B35, C35, 35R, D35, E35, F35, G35, H35, J35, K35, M35, 35-33, N35, 35-A33, 35-B33, P35, S35, 35-C33, E-33, F-33, G-33, V35, V35A, V35B, 35-C33A, E33A, E33C, 36, A36, F33A, F33C, A36TC, B36TC, 23, A23, A23A, A23-19, A23-24, A24, 19A, M19A, B19, B23, C23, A24R, B24R, C24R	Wilco (800) 767-7593 (316) 943-9379	STC# SA00638WI	RG-35A RG-35AXC RG24-16	FAA-PMA Supplement No. 37, dd 06/22/98 Amended: dd 06/29/98 & FAA-PMA Supplement No. 82, dd 07/18/07 (to add RG24-16)

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
B-N Group Ltd.	BN-2, BN-2A, BN-2A-2, BN-2A-3, BN-2A-6, BN-2A-8, BN-2A-9, BN-2A-20, BN-2A-21, BN-2A-26, BN-2A- 27, BN-2B-20, BN-2B-21, BN-2B-26, BN- 2B-27, BN-2T, BN-2T-4R	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E	FAA-PMA Supplement No. 34, dd 11/18/97 and FAA TSO-C173
Bell	206A & 206B (To replace nickel-cadmium battery – Contact Adv. Pwr. for details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00318SE	RG-206	FAA-PMA Supplement No. 26, dd 06/21/96 and FAA TSO-C173
Bell	206A & 206B (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09054RC	RG-206	FAA-PMA Supplement No. 23, dd 04/04/96 and FAA TSO-C173
Bell	204B, 205B, 205A-1, 212, 412 (To replace nickel-cadmium battery – Contact Adv. Pwr. for details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00173SE	RG-380E/44	FAA-PMA Supplement No. 20, dd 11/13/95 and FAA TSO-C173
Bell	212 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Bell	214ST (To replace nickel-cadmium battery – Contact Falcon Crest for replacement details prior to battery purchase) (Battery avail. through STC holder)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09225RC	RG-214	FAA-PMA Supplement No. 45, dd 10/22/02
Bell	222U (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09142RC	RG-380E/44	FAA-PMA Supplement No. 30, dd 05/18/97 and FAA TSO-C173
Bell	212, 412, 412EP (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09053RC	RG-380E/44	FAA-PMA Supplement No. 23, dd 04/04/96 and FAA TSO-C173
Bell	206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC & STA# SR09069RC	RG-222	FAA-PMA Supplement No. 25, dd 06/07/96 and FAA TSO-C173
Bell	206L, 206L-1, 206L-3, 206L-4 (To replace nickel-cadmium battery – Contact Adv. Pwr. for details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00462SE	RG-222	FAA-PMA Supplement No. 48, dd 12/02/02 and FAA TSO-C173
Bell	407 (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase) (Battery available through STC holder)	Falcon Crest Av. (800) 833-5422 (713) 644-2290	STC# SR09359RC	RG-407A1	FAA-PMA Supplement No. 58, dd 06/19/03
Bell	407, 430 (To replace nickel-cadmium battery – Contact Rotorcraft for details prior to battery purchase)	Rotorcraft Support (818) 997-7667	STC# SR01456LA	RG-407	FAA-PMA Supplement No. 62, dd 10/30/03 and FAA TSO-C173 Supplement amended 10/04/2012 to inc. Bell 430
Boeing	737-600, -700, -800, -900 Series (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST03932AT (Kit)	RG-380E/60B 9507 (Dummy Temperature Plug)	FAA-PMA Supplement No. 96, dd 09/28/11 and P/N RG-380E/60B is FAA TSO-C173 authorized
Bombardier Inc.	BD-100-1A10 (Challenger 300) (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01488WI (Kit)	RG-441 5-0123 (Kit, Temp Sensor TS-C3)	FAA-PMA Supplement No. 85, dd 01/07/09 & P/N RG-441 is FAA TSO-C173 authorized.
Bombardier Inc.	CL-600-2B16, -2B19, -2C10, -2D24 (To replace nickel-cadmium batteries – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 756-0303	STC# ST01646WI (Kit)	RG-380E/44L (APU); RG-223 (Main); 5-0166 (Kit, Temp. Sensor TS-C11A); 5-0283 (Kit, Temp. Sensor TS-C11B)	FAA-PMA Supplement No. 99, dd 01/13/12 and P/N RG-380E/44L & RG-223 are FAA TSO-C173 authorized.
Bombardier Inc.	DHC-8-100, -200, -300 (To replace nickel-cadmium batteries – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 756-0303	STC# ST01643WI (Kit)	RG-380E/44 or RG-380E/60L & 5-0290 (Plug, Dummy TS)	FAA-PMA Supplement No. 95, dd 09/09/11 and RG-380E/44 & RG-380E/60L are FAA TSO-C173 authorized
British Aerospace	Jetstream 3101 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2994SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92 and FAA TSO-C173
British Aerospace	Jetstream 3201 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2995SO	RG-390E	FAA-PMA Supplement No. 16, dd 05/18/92 and FAA TSO-C173
British Aerospace	Jetstream 3201 (S/N: 790 – 9999) (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00342LA	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 32, dd 06/11/97 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Cessna	<p>SINGLE ENGINE MODELS</p> <p>120, 140, 140A, 150, 150A, 150B, 150C, 150D, 150E, 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, 152, A152, 170, 170A, 170B, 172, 172A, 172B, 172C, 172D, 172E, 172F (USAF T-41A), 172G, 172H (USAF T-41A), 172I, 172K, 172L, 172M, 172N, 172P, 172Q, 172R, 172S, 175, 175A, 175B, 175C, P172D, R172E (USAF T-41B)(USAF T41C&D), R172F(USAF T-41D), R172G ((USAF T-41C & T-41D), R172H (USAF T-41D), R172J, R172K, 172RG, 177, 177A, 177B, 177RG, 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R/T182, R182, TR182, 182S, 182T, T182T, 185, 185A, 185B, 185C, 185D, 185E, A185E, A185F, 188, 188A, A188, A188A, 188B, A188B, T188C, 190, 195, 195A, 195B, 206, 206H, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, U206G/TU206G, T206H, 207/T207, 207A/T207A, 305B, 305E, 210, 210A, 210B, 210C, 210D, 210E, 210F, T210F, 210G, T210G, T210H, 210H, T210J, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N, P210N, T210N, 210R, P210R, T210R, 210-5 (205), 210-5A (205A), 305B, 305E (Military TO-1D, O-1D, O-1F), 337, 337A (USAF O2B), 337B, 337C, 337D, 337E, 337F, 337G, 337H/T337H, T337B, T337C, T337D, T337E, T337F, T337G, M337B (USAF O2A), P337H, T337H-SP</p> <p>TWIN ENGINE MODELS</p> <p>T303, 310, 310A (USAF U-3A), 310B, 310C, 310D, 310E (USAF U-3B), 310F, 310G, 310H, E310H, E310I, E310J, 310J, 310J-1, E310K, 310L, 310N, 310P, T310P, 310Q, T310Q, 310R, T310R, 320, 320-1, 320A, 320B, 320C, 320D, 320E, 320F, 335, 340, 340A, 401, 401A, 401B, 402, 402A, 402B, 402C, 404, 411, 411A, 414, 414A, 421, 421A, 421B, 421C</p>	Concorde Battery (800) 757-0303	STC# SA01118WI (See Note 3)	<p>RG-25 RG-25XC Replaces original battery p/n 0511319-1</p> <p>RG-35A RG-35AXC Replaces original battery p/n 0712605-1 or 0712604-1 or 0311053</p> <p>RG24-12 RG24-16 (P/N RG24-11 and RG24-15 are approved for installation, but are not recommended due to some fitment issues.) Replaces original battery p/n C614001-0106</p> <p>RG24-15M Replaces original battery p/n C614002-0102</p> <p>RG24-10 (P/N RG24-9 is approved for installation, but not recommended due to some fitment issues) Replaces original battery p/n C614001-0105</p> <p>RG24-20 Replaces original battery p/n 5018200-201 & REBAT p/n R2425</p>	FAA-PMA Supplement No. 83, dd 9/20/07 Amended 10/21/09
Cessna	<p>120, 140, 140A, 170, 170A, 170B, 172 thru 172Q, 172R, 172S, 210, 210A thru 210R, T210F thru T210R, P210N, P210R, 210-5, 210-5A, 175, 175A, 175B, 175C, 172RG, P172D, R172E, R172F thru R172K, 177, 177A, 177B, 177RG, 180, 180A thru 180K, 185, 185A thru 185E, A185E, A185F, 188, 188A, 188B, A188, A188A, A188B, T188C, 206, U206, P206, U206A, P206A, P206B, TU206A, TU206B, TP206A, TP206B, U206B, P206C/TP206C thru P206E/TP206E, U206C/TU206C thru U206G/TU206G, 206H, 207, 207A, T207, T207A, 305B, 305E, 337, 337A thru 337H T337B thru T337H, M337B, P337H, T337H-SP, 150, 150A thru 150M, A150K thru A150M, 152, A152</p>	Wilco (800) 767-7593 (316) 943-9379	STC# SA00897WI (See Note 3)	<p>RG-25 or RG25XC Replaces original battery p/n 0511319-1</p> <p>RG-35A or RG35AXC Replaces original battery p/n 0712605-1</p> <p>RG24-11 RG24-15 Replaces original battery p/n C614002-0102</p> <p>RG24-11M RG24-15M Replaces original battery p/n C614001-0106</p>	FAA-PMA Supplement No. 43, dd 09/04/01

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Cessna	210 (S/N: 21059503 & on), T210	Wilco (800) 767-7593 (316) 943-9379	STC# SA2558CK	RG24-11M	FAA-PMA Supplement No. 14, dd 02/07/91
Cessna	182, 182A, 182B, 182C, 182D, 182E, 182F, 182G, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R, R182/TR182, 182R/T182 (182 through S/N: 18265965 except: 18263479)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00753WI	RG-35A RG-35AXC	FAA-PMA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	182 Series (S/N:18263479, 18265966 and up), R182 and TR182 Series (S/N: R18200001 and up)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00753WI	RG24-15	FAA Supplement No. 41, dd 08/16/01 Amended: dd 08/13/02
Cessna	425 (Conquest I) (To replace nickel-cadmium battery – Contact Wilco for details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2435CE	RG-380E/44	FAA-PMA Supplement No. 14, dd 02/07/91 and FAA TSO-C173
Cessna	441 (Conquest II) (To replace nickel-cadmium battery – Contact Wilco for details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA2496CE	RG-380E/44	FAA-PMA Supplement No. 14, dd 02/07/91 and FAA TSO-C173
Cessna	550 (Citation II) Series (To replace nickel-cadmium batteries – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01639LA	RG-131	FAA TSO-C173
Cessna	(Caravan) 208, 208B (Replaces p/n RG-380E/44 or RG-380E/40B w/ two (2) RG-390E in conjunction with engine conversion)	Texas Turbine Conversions (972) 382-4402	STC# SA10841SC	RG-390E	FAA-PMA Supplement No. 89, dd 10/27/09 and FAA TSO-C173
Cessna	(Caravan) 208, 425, 441, (Citation II) 500, 501, 550, 551 (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Cirrus	SR20, SR22	Concorde Battery (800) 757-0303	STC# SA01304WI	RG24-11M, RG24-15M	FAA-PMA Supplement No. 76, dd 02/18/05
Dassault	Falcon 10 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00774LA (Kit)	RG-390E, 9899 (Temp. Sensor Tray)	FAA-PMA Supplement No. 39, dd 04/23/99 P/N RG-390E is FAA TSO-C173 authorized
Dassault	Falcon 20 Series, C, D, E, F (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Dassault	Falcon 50, 50EX, 900, 900EX, 900DX, 2000, 2000EX (Emergency battery replacement only to replace nickel-cadmium or lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01571WI	RG-128 Series	FAA-PMA Supplement No. 90, dd 02/12/10 and FAA TSO-C173
Dassault	MF 50 (To replace nickel-cadmium battery – Contact Concorde for replacement details prior to battery purchase) (Battery Mod. avail. through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
Dassault	Falcon MF900, F900EX To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase) (Battery Mod. avail. through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390E/LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
Dassault	Falcon 2000 To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase) (Battery Mod. avail. through Dassault)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44LS	FAA-PMA Supplement No. 51, dd 02/21/03 and FAA TSO-C173
de Havilland Aircraft	See Bombardier Inc. & Viking Air Ltd				
Dornier	328-100	Concorde Battery (800) 757-0303	STC# ST00732DE	RG-380E/44LS	FAA-PMA Supplement No. 98, dd 11/10/11
Embraer	EMB-110P1, EMB-110P2 (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Embraer	135BJ, 135ER, 135LR, 135KE, 135KL, 145, 145EP, 145ER, 145LR, 145MP 145MR, 145XR (To replace nickel-cadmium battery - Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST01520WI (Kit)	RG-442 (Battery) 5-0124 (Kit, Temp. Sensor TS-C4)	FAA-PMA Supplement No. 86, dd 03/09/09 & P/N RG-442 is FAA TSO-C173 authorized.
Embraer	EMB-500 (Phenom 100) (To replace lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA01633WI	RG-390E	FAA-PMA Supplement No. 94, dd 09/09/11 and FAA TSO-C173
Embraer	EMB-505 (Phenom 300) (To replace lead-acid batteries – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA01703WI	RG-380E/44 (Main) RG-390E (Opt Aux) 7000 (Spacer – Opt Aux Battery)	FAA-PMA Supplement No. 102, dd 12/14/12 and FAA TSO-C173 (batteries only)

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Enstrom Helicopter	F-28F & 280FX	Enstrom Helicopter (906) 863-1200	TC# H1CE, Rev. 20, Rev. A	RG24-11M (24V) & RG-35A (12V)	FAA-PMA Supplement No. 23, dd 04/04/96
Erco / Ercoupe	(See Univair)				
Eurocopter	(See Airbus Helicopters)				
Fairchild Aircraft	(See M-7 Aerospace)				
Garlick Helicopters	Bell UH-1F, UH-1P, TH-1F (To replace nickel-cadmium battery – Contact Tamarack for details prior to battery purchase)	Tamarack Helicopters (406) 777-1044	(Omitted temporarily pending STC number correction)	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03 and FAA TSO-C173
Global Amphibians	(See Revo Inc.)				
Globe	GC-1A, GC-1B	Swift Museum Foundation (423) 745-9547	TC# A-766	RG-35A	FAA-PMA Supplement No. 63, dd 10/30/03
Grumman Aircraft	(See True Flight Holdings LLC)				
Gulfstream Aerospace	Galaxy/Gulfstream 200	Gulfstream Aerospace (214) 902-7770	STC# ST09945SC	5-0122 (Kit, Temp. Sensor TS-C2A)	FAA-PMA Supplement No. 87, dd 04/13/09
Gulfstream Aerospace	(Gulfstream I) G-159 (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Gulfstream Aerospace	GII (G-1159), GIII (G-1159A), GII (G-1159B) (DC System) (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00773LA	RG-380E/44	FAA-PMA Supplement No. 40, dd 04/30/99 and FAA TSO-C173
Gulfstream Aerospace	GIII (G-1159A)(s/n 357, 402 & up), GIV (AC System) (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00544LA (Kit)	RG-380E/44, 9713 (Adaptor, Charger)	FAA-PMA Supplement No. 38, dd 11/02/98 and FAA TSO-C173
Hawker Beechcraft	See Beechcraft Corporation				
Israel Aircraft	(Jet Commander) 1121, 1121A, 1121B (Westwind) 1123, 1124 (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
JetProp LLC	Piper PA-46-310P, PA-46-350P (Included as part of STC for turbine conversion)	Rocket Eng. / Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-46	FAA-PMA Supplement No. 54, dd 04/29/03
JetProp LLC	Piper PA-46-310P, PA-46-350P (Higher Capacity Replacement) (Included as part of STC for turbine conversion)	Rocket Eng. / Jet Prop LLC (509) 535-4401	STC# ST00541SE	RG-49	FAA-PMA Supplement No. 54, dd 04/29/03 and FAA TSO-C173
Kaman Aerospace	K1200	Concorde Battery (800) 757-0303	TC# TR7BO	RG-380E/40B	FAA-PMA Supplement No. 26, dd 06/21/96 and FAA TSO-C173
Lake	(See Revo Inc.)				
Learjet	23, 24, 25, 28, 29, 35, 36, 55 (To replace flooded lead-acid battery – Contact Concorde for replacement details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Learjet	40, 45 (To replace Concorde part no. RG-443 – Contact the STC holder for details prior to battery purchase) (STC for emergency battery only)	Global Aviation Tech. (316) 425-0998	STC# ST01639WI (Kit)	RG-145-2	FAA-PMA Supplement No. 93, dd 09/09/11 and FAA TSO-C173
Learjet	45 (To replace lead-acid emergency battery – Contact Concorde for replacement details prior to battery purchase) (STC for emergency battery only)	Concorde Battery (800) 757-0303	STC# ST01173WI	RG-443	FAA-PMA Supplement No. 59, dd 06/23/03

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
M-7 Aerospace	Fairchild SA226-AT, SA227-AT, SA226-T, SA227-CC, -DC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 60, dd 06/25/03 and FAA TSO-C173
M-7 Aerospace	Fairchild SA227AC, SA227BC (RG-390ES replaces M-7 Aerospace p/n FASRG390ESTC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-390ES	FAA-PMA Supplement No. 17, dd 06/27/95 and FAA TSO-C173
M-7 Aerospace	Fairchild SA226-T, SA226-T(B), SA227-TT (To replace p/n RG-91A which replaces M-7 Aerospace p/n FASRG91STC)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-91	FAA-PMA Supplement No. 69, dd 05/17/04
Maule Aerospace Technology Inc.	M-4-210, M-4-220, M-4-180, M-5-180, M-5-210, M-5-220, M-5-235, M-5-210TC, M-5-200, M-6-180, M-6-235, M-7-235, M-7-235A, M-7-235B, M-7-235C, M-7-260, M-7-260C, M-8-235, MT-7-235, MT-7-260, MX-7-160, MX-7-160C, MX-7-180, MX-7-180A, MX-7-180B, MX-7-180C, MX-7-180AC, MX-7-235, MXT-7-160, MXT-7-180, MXT-7-180A	Maule Aerospace (229) 985-2045	FAA Design Approval	RG-35A RG-35AXC	FAA-PMA Supplement No. 64, dd 01/06/04
MD Helicopter	MD369, 369A, 369D, 369F, 369FF, 369H, 369HM, 369HS, 369HE, 369E and 500N (To replace nickel-cadmium battery – Contact Adv. Pwr. for details prior to battery purchase)	Advanced Power (877) 522-8837 (626) 969-7227	STC# SR00716SE (Kit)	RG-500 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 47, dd 12/02/02 & P/N RG-500 is FAA TSO-C173 authorized
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on right side of battery container – Used for most 600N models)	Concorde Battery (800) 757-0303	STC# SR01564LA (Kit)	RG-600-1 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 67, dd 02/06/04 & P/N RG-600-1 is FAA TSO-C173 authorized
MD Helicopter	600N (To replace nickel-cadmium battery with the connector receptacle on left side of battery container)	Concorde Battery (800) 757-0303	STC# SR01564LA	RG-600-2 CBP-3349-2W (Connector – Selling p/n 4002) 9542 (Adaptor)	FAA-PMA Supplement No. 67, dd 02/06/04 & P/N RG-600-2 is FAA TSO-C173 authorized
MD Helicopter	MD-900 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR03895AT (Kit)	RG-407 Elbow Coupling Assy #5-0349 (Assy includes #8003, Elbow, Vent Adaptor, & #8086 Coupling)	FAA PMA Supplement No. 92, dd 09/09/11 & P/N RG-407 is FAA TSO-C173 authorized.
Mitsubishi	MU-2B, MU-2B-10, -15, -20, -25, -26, -26A, 30, 35, 36, 36A, 40, 60, MU-300-1, -1A (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Mitsubishi	YS-11A Series (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SA2795SO	RG-390E	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173
Mooney	M20 (w/ R-33 or R-35 battery), M20A (w/ R-33 or R-35 battery), M20B, -20C, -20D, -20E, -20F, M20G, M20J (S/N 24-0001 to 24-2999), M20K (S/N 25-0001 to 25-0999)	Concorde Battery (800) 757-0303	Identity per 14 CFR § 21.303	RG-35A (To replace R-33) or RG-35AXC (To replace R-35)	FAA-PMA Supplement No. 77, dd 03/01/05
Mooney	M20J, M20K	STC/Mooney Ltd. (830) 792-2918	STC# SA00081SE & STC# SA5691NM	RG-35A	FAA-PMA Supplement No. 24, dd 05/06/96
Mooney	M20J, M20K, M20L, M20M, M20R, M20S, M20TN (24V models)	Concorde Battery (800) 757-0303	Identity per 14 CFR § 21.303	RG24-11M (to replace manifold battery) OR RG24-15	FAA-PMA Supplement No. 84, dd 02/01/08

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Piaggio Aero Industries SpA	P180	Concorde Battery (800) 757-0303	STC# SA01653LA (Kit)	RG-380E/40L (Battery) 5-0242 (Kit, Temp. Sensor TS-C6A)	FAA-PMA Supplement No. 74, dd 09/27/04 & P/N RG-380E/40L is FAA TSO-C173 auth.
Pilatus Britten Norman Ltd.	(See B-N Group Ltd.)				
Pilatus	PC-12 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# ST00776LA	RG-380E/44	FAA-PMA Supplement No. 39, dd 04/30/99 and FAA TSO-C173
Piper	PA-12, PA-12S, PA-18, PA-18 "105" (Special), PA-18 "125" (Army L-21B), PA-18 "135" (Army L-21B), PA-18 "150", PA-18A, PA-18A "135", PA-18A "150", PA-18S, PA-18S "105", PA-18S "125", PA- 18S "135", PA-18S "150", PA-18AS "125", PA-18AS "135", PA-19 (Army L-18C), PA-19S, PA-20, PA- 20 "115", PA-20 "135", PA-20S, PA-20S "115", PA-20S "135", PA-22, PA-22-108, PA-22-135, PA-22-150, PA-22-160, PA-22S-135, PA-22S-150, PA-22S-160, PA-23, PA-23-160, PA-23-235, PA-23-250 (Navy UO-1), PA-E23-250, PA-24, PA-24-250, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-28-140, PA-28-150, PA-28-151, PA-28-160, PA-28-161, PA-28-180, PA-28-181, PA-28-201T, PA-28-235, PA-28-236, PA-28R-180, PA-28R-200, PA-28R-201, PA-28R-201T, PA-28RT-201, PA-28RT-201T, PA-28S-160, PA-30, PA-31, PA-31-300, PA-31-350 & T-1020, PA-31-325 C/R, PA-32-260, PA-32-300, PA-32-301, PA-32-301T, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301, PA-32R-301T, PA-34-200, PA-34-200T, PA-34-220T, PA-36-285, PA-36-300, PA-36-375, PA-36-285, PA-38-112, PA-39, PA-40, PA-44-180, PA- 44-180T TURBO, PA-46-310P, PA-46-350P, PA-60-600, PA- 60-601, PA-60-601P, PA-60-602P, PA-60-700P, PA-400	Concorde Battery (800) 757-0303	STC# SA01147WI (See Note 3)	RG-25 RG-25XC Replaces original battery p/n 450- 030 RG-25 Replaces original battery p/n 450- 022 RG-35A RG-35AXC Replaces original battery p/n 450-035 RG24-11 RG24-15 RG24-16 Replaces original battery p/n 450- 027 or 450-032 RG24-11M RG24-15M Replaces original battery p/n 450- 101 RG24-20 Replaces original battery p/n 450- 028, 450-031 or 450-029 (Please note an installation kit may be required)	FAA-PMA Supplement No. 50, dd 3/7/03 and FAA-PMA Supplement No. 103, dd 2/26/13 (RG24-16 only)

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Piper	PA-12, PA-12S PA-18, PA-19 (Army L-18C), PA-18 "125" (Army L-18A) , PA-18 "135" (Army L-21B), PA-18A, PA-18A "135", PA-18 "105", PA-18S, PA-19S, PA-18S "125", PA-18S "135", PA-18AS "125", PA-18AS "135", PA-18S "105", PA-18 "150", PA-18A "150", PA-18S "150", PA-18A, PA-18A "135", PA-18A "150" PA-20, PA-20 "115", PA-20S, PA-20S "115", PA-20S "135", PA-20 "135", PA-22, PA-22-135, PA-22S-135, PA-22-150, PA-22S-150, PA-22-160, PA-22S-160, PA- 22-108, PA-24, PA-24-250, PA-24-400, PA-24-260, PA-25, PA-25-235, PA-25-260, PA-23, PA-23, PA-23-160, PA-23-250 (Navy UO-1), PA-28-160, PA-28-150, PA-28-180, PA-28S-160, PA-28S-180, PA- 28-235, PA-28-140, PA-28R-200, PA-28-151, PA-28-181, PA-28-161, PA-28R-201, PA-28R-201T, PA-28-236, PA-28RT-201, PA-28RT-201T, PA-28-201T, PA-32-260, PA-32-300, PA-32S-300, PA-32R-300, PA-32RT-300, PA-32RT-300T, PA-32R-301 (SP), PA-32R-301 (HP), PA-32R-301T, PA-32-301, PA-32-301T, PA-38-112, PA-36-285, PA-36-300, PA-36-375, PA-46-310P, PA-46-350P	Wilco (800) 767-7593 (316) 943-9379	STC# SA00954WI (See Note 3)	RG-25 or RG-25XC Replaces original battery p/n 450-030 RG-35A or RG-35AXC Replaces original battery p/n 450-035 RG24-11 or RG24-15 Replaces original Battery p/n 450-032 RG24-11M or RG24-15M Replaces original battery p/n 450-101 RG24-20 Replaces original battery p/n 450-031	FAA-PMA Supplement No. 43, dd 09/04/01
Piper	PA-23 Apache, PA-23-160, PA-23-250 (Navy UO-1), PA-23-235, PA-E-23-250 Aztec, PA-23-250, PA-31 Navajo, PA-31- 300 Navajo, PA-31-350 Chieftan & T-1020, PA-31-325 Navajo C/R, PA-44-180 Seminole, PA-44-180T Turbo Seminole, PA-30 Twin Comanche, PA-39 Twin Comanche, PA-40 Twin Comanche, PA- 34-200 Seneca, PA-34-200T Seneca II, PA-34-220T Seneca III, IV, V	Wilco (800) 767-7593 (316) 943-9379	STC# SA00954WI (See Note 3)	RG-25 or RG-25XC Replaces p/n 450-030 RG-35A or RG-35AXC Replaces p/n 450-035 RG24-11 or RG24-15 Replaces p/n 450-032 RG24-11M or RG24-15M Replaces p/n 450-101 RG24-20 Replaces p/n 450-031	FAA-PMA Supplement No. 61, dd 07/14/03
Piper	(Cheyenne) PA-31T, PA-31T1, PA-31T2, PA-31T3, PA-42, PA-42-720, PA-42-1000 (To replace nickel-cadmium battery – Contact Wilco for details prior to battery purchase)	Wilco (800) 767-7593 (316) 943-9379	STC# SA00843WI	RG-380E/44L RG-380E/44K RG-380E/60L RG-380E/60K	FAA-PMA Supplement No. 80, dd 12/02/05 and FAA TSO-C173
Pitts	(See Aviat)				
Polskie Zakłady Lotnicze Sp. z o.o.	PZL M28 05 (To replace nickel-cadmium battery and temperature sensor – Contact Concorde for details prior to battery/sensor purchase)	Concorde Battery (800) 756-0303	TC# A56CE	RG-CIS25, 5-0263 (Kit, Temp. Sensor TS-C10)	FAA-PMA Supplement No. 106, dd 9/15/14
Raytheon	(See Beechcraft)				
Revo Inc.	(Lake) LA-4, LA-4-200, Model 250 (S/N: 1-25 only)	Revo Inc. (Phone unknown)	FAA Design Approval	RG-35A or RG-35AXC	FAA-PMA Supplement No. 25, dd 06/07/96
Robinson Helicopter	R-22	Robinson Helicopter (310) 539-0508	TC# H10WE	RG-25XC	FAA-PMA Supplement No. 75, dd 02/18/05
Robinson Helicopter	R-44	Robinson Helicopter (310) 539-0508	TC# H11MN	RG-25XC (12V), RG24-15 (24V)	FAA-PMA Supplement No. 75, dd 02/18/05
Sabreliner	NA 265, NA 265-20, -30, -40, -70, -80 (To replace flooded lead-acid battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44 or RG-380E/40B	FAA-PMA Supplement No. 15, dd 01/06/92 and FAA TSO-C173

Manufacturer	Model & Certificate Notes	Certificate Holder	Certificate No. (or FAA Design Approval)	CBC Part Number ⁷	Battery / Part FAA Approval Type
Sabreliner	265-40, -60, -65, -70, -80 (To replace nickel-cadmium battery – Contact Jet Harbor for details prior to battery purchase)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-380E/44	FAA-PMA Supplement No. 36, dd 04/20/98 and FAA TSO-C173
Sabreliner	265-65 (To replace nickel-cadmium battery – Contact Jet Harbor for details prior to battery purchase)	Jet Harbor Inc. (954) 772-2863	STC# ST01294AT	RG-206	FAA-PMA Supplement No. 36, dd 04/20/98 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-30 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 29, dd 01/17/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-30 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126	FAA-PMA Supplement No. 29, dd 01/17/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-60 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97 and FAA TSO-C173
Short Brothers & Harland Ltd.	SD 3-60 (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	FAA Design Approval	RG-126	FAA-PMA Supplement No. 28, dd 01/17/97 Amended: dd 02/21/97 and FAA TSO-C173
Sikorsky	CH-54B	Helicopter Transport (541) 754-2400	STC# SR01241SE	RG-390E	FAA-PMA Supplement No. 78, dd 3/2/05 and FAA TSO-C173
Sikorsky	S-76A (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC# SR00091LA	RG-380E/40B	FAA-PMA Supplement No. 19, dd 08/24/95 and FAA TSO-C173
Sikorsky	S-76B (To replace nickel-cadmium battery – Contact Concorde for details prior to battery purchase) (Two each RG-390E req.)	Concorde Battery (800) 757-0303	STC# SR03819AT	RG-390E	FAA-PMA Supplement No. 91, dd 04/09/10 and FAA TSO-C173
Sikorsky	S-76A, C, C+ (To replace nickel-cadmium battery – Contact Falcon Crest for details prior to battery purchase)	Falcon Crest Av. (800) 833-5422 (713) 644-2292	STC & STA# SR09050RC	RG-380E/44	FAA-PMA Supplement No. 22, dd 01/23/96 and FAA TSO-C173
Slingsby Aviation	Firefly Models T67M260 & T67M260-T3A	Slingsby Aviation (011) (44) (1751) 432474	TC# A73EU Rev. 2 BA 17, Issue 6	RG24-11M	FAA-PMA Supplement No. 27, dd 07/03/96
Socata	(See Airbus Group Supply)				
Stinson	(See Univair)				
Tamarack Helicopters	Bell UH-1F, TH-1F, UH-1P (To replace nickel-cadmium battery – Contact Tamarack for details prior to battery purchase)	Tamarack Helicopters (406) 777-0144	STC# SR01349LA	RG-390E	FAA-PMA Supplement No. 53, dd 03/26/03 and FAA TSO-C173
Tiger Aircraft	(See True Flight Holdings LLC)				
True Flight Holdings LLC	AA-1, AA-1A, AA-1B, AA-1C, AA-5, AA-5A, AA-5B, AG-5B	Concorde Battery (800) 757-0303	STC# SA01250WI	RG-25 or RG-25XC; RG24-11M or RG24-15M	FAA-PMA Supplement No. 71, dd 06/04/04
Twin Commander	680T, 680V, 680W, 690, 690A, 690B, 690C, 695, 695A, 690D & 695B	Concorde Battery (800) 757-0303	FAA Design Approval	RG-380E/44	FAA-PMA Supplement No. 15, dd 01/06/91 and FAA TSO-C173
Univair (Erco)	415-C, 415-D, 415-CD (S/N 113 and up)	Univair (303) 375-8882	TC# A-718 Rev. 29, dd 07/14/05	RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Erco: 415-E, 415-G, 415F-1 (All S/N's) Forney: F-1A (S/N 5715 – 5729)	Univair (303) 375-8882	TC# A-787 Rev. 33, dd 07/14/05	RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Erco)	Forney: F-1A (S/N 5730 and up) Alon: A-2, A-2A; Mooney M-10	Univair (303) 375-8882	TC# A-787 Rev. 33, dd 07/14/05	RG-25	FAA-PMA Supplement No. 79, dd 11/23/05
Univair (Stinson)	Stinson: 108, 108-1, 108-2, 108-3, 108-5	Univair (303) 375-8882	TC# A-767 Rev. 27, dd 07/14/05	RG-35A	FAA-PMA Supplement No. 79, dd 11/23/05
Viking Air Ltd	DHC-6-1, -100, -200, -300 (To replace nickel-cadmium battery or lead-acid – Contact Concorde for details prior to battery purchase)	Concorde Battery (800) 757-0303	STC#SA03971AT	RG-380E/60L or RG-380E/44 (Main) RG-300 (Aux.- Optional) 5-0455 (Mating Connector) (Aux – Optional) 4000 (Connector) (AN-3150 lead-acid replacement only)	FAA-PMA Supplement No. 101, dd 08/20/12 and FAA TSO-C173 (batteries only)

The Concorde batteries listed below are authorized per FAA TSO-C173

(See note 4)

CBC Battery Part number	Date of Approval
RG-42 and RG-42[]	May 27, 2011
RG-47 and RG-47[]	July 1, 2010
RG-49 and RG-49[]	July 1, 2010
RG-121 Series	December 3, 2007
RG-122 Series	December 3, 2007
RG-125	July 31, 2008
RG-126	July 31, 2008
RG-128 Series	June 25, 2008
RG-129 Series	June 25, 2008
RG-131	January 3, 2008
RG-132	June 25, 2008
RG-145-1 and RG-145-1[]	November 5, 2010
RG-145-2 and RG-145-2[]	November 5, 2010
RG-150-1	January 8, 2008
RG-150-2	January 8, 2008
RG-206 and RG-206[]	July 1, 2010
RG-222 and RG-222[]	March 27, 2009
RG-223 and RG-223[]	May 27, 2011
RG-224 and RG-224[]	May 27, 2011
RG-300 and RG-300[]	June 15, 2012
RG-325 and RG-325[]	February 29, 2012
RG-350 and RG-350[]	July 1, 2010
RG-355 and RG-355[]	July 1, 2010
RG-380E/40B and RG-380E/40B[]	September 9, 2008
RG-380E/40K and RG-380E/40K[]	September 9, 2008
RG-380E/40KS and RG-380E/40KS[]	September 9, 2008
RG-380E/40L and RG-380E/40L[]	September 9, 2008
RG-380E/40LS and RG-380E/40LS[]	September 9, 2008
RG-380E/44 and RG-380E/44[]	August 15, 2008
RG-380E/44K and RG-380E/44K[]	August 15, 2008
RG-380E/44KS and RG-380E/44KS[]	August 15, 2008
RG-380E/44L and RG-380E/44L[]	August 15, 2008
RG-380E/44LS and RG-380E/44LS[]	August 15, 2008
RG-380E/44KH and RG-380E/44KH[]	February 29, 2012
RG-380E/44KSH and RG-380E/44KSH[]	February 29, 2012
RG-380E/44LH and RG-380E/44LH[]	February 29, 2012
RG-380E/44LSH and RG-380E/44LSH[]	February 29, 2012
RG-380E/46 and RG-380E/46[]	October 5, 2012
RG-380E/46L and RG-380E/46L[]	October 5, 2012
RG-380E/46LS and RG-380E/46LS[]	October 5, 2012
RG-380E/46K and RG-380E/46K[]	October 5, 2012
RG-380E/46KS and RG-380E/46KS[]	October 5, 2012
RG-380E/60B and RG-380E/60B[]	November 4, 2010
RG-380E/60K and RG-380E/60K[]	July 29, 2009
RG-380E/60KS and RG-380E/60KS[]	July 29, 2009
RG-380E/60L and RG-380E/60L[]	July 29, 2009
RG-380E/60LS and RG-380E/60LS[]	July 29, 2009
RG-390E and RG-390E[]	October 20, 2008
RG-390ES and RG-390ES[]	October 20, 2008
RG-390E/L and RG-390E/L[]	October 20, 2008
RG-390E/LS and RG-390E/LS[]	October 20, 2008
RG-390E/25 and RG-390E/25[]	December 14, 2011
RG-390E/25S and RG-390E/25S[]	December 14, 2011
RG-390E/25L and RG-390E/25L[]	December 14, 2011
RG-390E/25LS and RG-390E/25LS[]	December 14, 2011
RG-400E/13	March 6, 2008
RG-407 and RG-407[]	March 29, 2011
RG-427 and RG-427[]	March 12, 2013
RG-441 and RG-441[]	November 7, 2008
RG-442 and RG-442[]	November 7, 2008
RG-500 and RG-500[]	July 1, 2010
RG-616 and RG-616[]	December 17, 2013
RG-641 and RG-641[]	April 1, 2014
RG-600 and RG-600[]	July 1, 2010
RG-1835-1 and RG-1835-2	February 19, 2009

The Concorde batteries and parts listed below are authorized per FAA TSO-C173a

(See note 5)

CBC Battery Part number	Description	Date of Approval
RG-150-1 and RG-150-1 []	Battery	April 29, 2014
MB-150-1	Subassembly	April 29, 2014
BS-150-A	Subassembly	April 29, 2014
RG-150-2 and RG-150-2 []	Battery	April 29, 2014
MB-150-2	Subassembly	April 29, 2014
RG-150-1[-Y] and RG-150-1[-Y] []	Battery	April 29, 2014
MB24-3.5-1	Subassembly	April 29, 2014
BS-150-C	Subassembly	April 29, 2014
RG-150-2[-Y] and RG-150-2 [-Y] []	Battery	April 29, 2014
MB24-3.5-2	Subassembly	April 29, 2014
RG-235 and RG-235 []	Battery	August 27, 2014
RG-380E/60KH	Battery	April 29, 2014
RG-380E/60KSH	Battery	April 29, 2014
RG-380E/60LH	Battery	April 29, 2014
RG-380E/60LSH	Battery	April 29, 2014
RG-390E/KH	Battery	April 29, 2014
RG-390E/KSH	Battery	April 29, 2014
RG-390E/LH	Battery	April 29, 2014
RG-390E/LSH	Battery	April 29, 2014

The Concorde parts listed below are authorized per FAA TSO-C173a Incomplete

(See note 6)

CBC Battery Part number	Description	Date of Approval
HCU-1	Heater Control Unit	August 29, 2013
HCU-2	Heater Control Unit	August 29, 2013
HCU-3	Heater Control Unit	August 29, 2013
HCU-4	Heater Control Unit	August 29, 2013
HCU-7X	Heater Control Unit	August 29, 2013

NOTES

Note 1 - Installations listed may require the battery purchase of an STC and/or STC Kit, aircraft modifications, etc. Contact the Concorde factory or the Certificate Holder for installation replacement details prior to battery purchase.

Note 2 - The products listed herein may be subject to export restrictions imposed by the United States. Export Licenses may be required. Customers are advised to contact Concorde for additional information on ECCN or USML information as it pertains to these products.

Note 3 – It is highly recommended for the aircraft's original battery part number to be confirmed prior to choosing a replacement battery listed on this STC. The original number should be carefully matched to the Concorde battery listed as the replacement to avoid an error in battery selection. Please note for some replacement model numbers, there are certain Concorde models that are preferred based on fitment. Other batteries listed are for PMA information only. The original battery part number is typically available in the aircraft parts catalog.

Note 4 – The batteries listed under TSO were approved under Technical Standard Order C173 by the US Federal Aviation Administration which applies to permanently installed, rechargeable lead-acid batteries intended to provide power for aircraft equipment including emergency and standby systems and electrical power to start aircraft engines or auxiliary power units when required. Those installing a battery listed, on or in a specific type or class of aircraft, must determine that the aircraft installation conditions are within the TSO Standards. TSO articles must have a separate approval for installation in an aircraft. This article may be installed only according to 14 CFR part 43 or the applicable airworthiness requirements.

Note 5 - The conditions and tests required for TSO approval of this article are minimum performance standards. It is the responsibility of those installing the article on or within a specific type or class aircraft to determine that the aircraft installation conditions are within the TSO standards. TSO articles must have separate approval for installation in an aircraft. The article may be installed only if performed under 14 CFR Part 43 or the applicable airworthiness requirements.

Note 6 – The conditions and tests required for TSO approval of this article are minimum performance standards. It is the responsibility of those installing the article on or within a specific type or class aircraft to determine that the aircraft installation conditions are within the TSO standards. TSO articles must have separate approval for installation in an aircraft. The article may be installed only if performed under 14 CFR Part 43 or the applicable airworthiness requirements. The TSO-C173a is incomplete and its functions are listed in the installation Component Maintenance Manual.

Note 7 – Please note Concorde's CB Series batteries have been removed from the Eligibility List due to product line discontinuation. If you have questions regarding the installation of a CB Series battery, please see www.concordebattery.com or contact Concorde's Customer Service Dept.